4DA 130203

SAFETY EVALUATION OF "PHOTO FINISH"

BY R. F. BIS D. L. WARBURTON C. A. FREEMAN G. F. HOFF L. A. KOWALCHIK M. E. DEGRABA E. LANIER J. H. BRUCE S. H. HAIRFIELD

RESEARCH AND TECHNOLOGY DEPARTMENT

3 NOVEMBER 1981

Approved for public release, distribution unlimited





NAVAL SURFACE WEAPONS CENTER

Dahlgren, Virginia 22448 • Silver Spring, Maryland 20910

83 07 01 005

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION	PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
I. REPORT NUMBER	2. GOVT ACCESSION NO.	3 RECIPIENT'S CATALOG NUMBER
NSWC TR 81-327	AD 1130 203	
4. TITLE (and Subtitle)		5. TYPE OF REPORT & PERIOD COMERED
SAFETY EVALUATION OF "PHOTO FINI	SH''	FINAL
		6. PERFORMING ORG. REPORT NUMBER
<u></u>		
7. AUTHOR(s) D. F. Ris, D. I. Workunton, C. A.	Emanman	8. CONTRACT OR GRANT NUMBER(3)
R. F. Bis, D. L. Warburton, C. A G. F. Hoff, L. A. Kowalchik, M.		•
E. Lanier, J. H. Bruce, S. H. Ha		
9. PERFORMING ORGANIZATION NAME AND ADDRES		10. PROGRAM ELEMENT, PROJECT, TASK
Naval Surface Weapons Center (Co		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
White Oak	20 1100)	
Silver Spring, MD 20910		0;
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
	•	3 November 1981
		13. NUMBER OF PAGES .
·		29
14. MONITORING AGENCY NAME & ADDRESS(If differ	ent from Controlling Office)	15. SECURITY CLASS. (of this report)
		UNCLASSIFIED
		III- OSCI ASSISICATION DOWNCOADING
		154. DECLASSIFICATION, DOWNGRADING
16. DISTRIBUTION STATEMENT (of this Report)		L
17. DISTRIBUTION STATEMENT (of the abstract entere	d in Block 20, il dillerent fro	m Report)
18. SUPPLEMENTARY NOTES		
13. KEY WORDS (Continue on reverse side if necessary) Lithium Battery Safety	and identify by block number)	
Li/So, batteries by-passed fuses	short cir forced di	
20. ABSTRACT (Cantinue on reverse side if necessary a	and identify by block number)	
Li/SO ₂ batteries are used to prostore "Photo Finish". This repodetermine if the system is safe	rt presents resul	air deployable expendable ts of a test program to
·		

DD 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE 5/N 0102-LF-014-6601

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

INCLASSIFIED RIVY CLASSIFICA	TION OF THIS PAG	E (When Date Ente	ored)			
						
			•			
	·				•	
		•		•		
						•
		•				
		•				
			•			
						•
	•					
	•					
	•					
				•		

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)

FOREWORD

Li/SO, batteries are used to provide power for an air deployable expendable store "PHOTO FINISH". This report presents results of a test program to determine if the system is safe for Fleet use.

Approved by:

MACK R. DIXON, Head Materials Division



では、100mmの

Acces	ssion For	
NTIS	GRA&I	
DTIC	TAB	
Unam	roanced	
Justi	Tication	
	ibution/	Codes
	Avail and	
Dist	Special	-
A		

CONTENTS

Chapter		Page
1	INTRODUCTION	1-1
2	EXPERIMENTAL	2-1
3	RESULTS AND DISCUSSION	3-1
4	CONCLUSIONS	4-1

	NSWC TR 81-327	
	ILLUSTRATIONS	
	•	
Figure		Page
1	SCHEMATIC OF "PHOTO FINISH" SHOWING LOCATION OF THERMOCOUPLES	
_	AND PRESSURE TRANSDUCER AS POSITIONED FOR TEST	2-2
2	PHOTOGRAPH OF BATTERY PACKAGE. THE POWER SUPPLIES USED TO	
-	POWER "PHOTO FINISH" ARE CONTAINED INSIDE THIS PACKAGE	2-3
3	SHORT CIRCUIT OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES.	
J	SHORT CIRCUIT CURRENT AND BATTERY VOLTAGES ARE INDICATED	
•	FOR EACH BATTERY. HOUSING PRESSURE AND BATTERY PACK	2.0
	TEMPERATURE ARE ALSO SHOWN	3-2
4	SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR	
	"PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR	
	WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR.	
	HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO	
	SHOWN	3-4
5	SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR	
	"PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO	
•	WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT.	
	HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO	
	SHOWN	3-5
6	SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR	
	"PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO	
	WERE DISCHARGED AT TUBER AMBERES WHILE THREE AND FOUR	
	WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO	
•	SHOWN	3-6
7	SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR	
,	"PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO	
	WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR	
	WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO	
	SHOWN. THE ENTIRE "PHOTO FINISH" UNIT WAS	
	PRECONDITIONED AT 71°C PRIOR TO DISCHARGE	3-7
	v	

ILLUSTRATIONS (Cont.)

Figure		Page
8	PHOTOGRAPH OF "PHOTO FINISH" UNIT WITH HEAT TAPE IN VICINITY OF BATTERY PACK	. 3-10
9	RESULTS OF EXTERNAL HEATING OF "PHOTO FINISH". THE BATTERY WAS HEATED AT APPROXIMATELY 10°C/MINUTE. BATTERY TEMPERATURE, VOLTAGES OF EACH BATTERY AND HOUSING PRESSURE ARE PLOTTED	3-11
10	RESULTS OF EXTERNAL HEATING OF "PHOTO FINISH". THE BATTERY WAS HEATED AT APPROXIMATELY 10°C/MINUTE. BATTERY TEMPERATURE, VOLTAGES OF EACH BATTERY AND HOUSING PRESSURE ARE PLOTTED	3-12
	TABLES	
Table .		Page
1 .	SUMMARY OF SHORT CIRCUIT DATA ON "PHOTO FINISH" (THROUGH 0.4 OHM LOAD)	3-3
2	CAPACITY (IN AMPERE HOURS) OF "PHOTO FINISH" BATTERIES TO A 2 VOLT/CELL CUTOFF	3-8
3	MEASURED VELOCITY AT WHICH NOSE CAP WAS EJECTED MAXIMUM PRESSURES ARE ALSO SUMMARIZED	3-9

CHAPTER 1

INTRODUCTION

A technical evaluation and safety analysis has been conducted on an air-deployable expendable store "PHOTO FINISH". The purpose of this report is to describe the results of a test program requested by NAVELEX (as required by reference 1) and conducted by the Naval Surface Weapons Center. The tests were conducted to determine if the unit was safe to handle, ship, and deploy as configured.

Abuse conditions were generated by:

- 1. Simultaneous short circuiting of the batteries with all fuses bypassed.
- Simultaneous discharge of each battery pack into voltage reversal with an external D.C. constant current power supply. Discharge currents were equal to the fuse value of each battery in the pack.
- 3. Heating of the batteries to 500°C at a rate of 20°C/min.

"PHOTO FINISH" is composed of four separate batteries described below:

- Battery number one has thirteen L026SH lithium sulfur dioxide cells wired in series.
- 2. Battery number two has four LO26SH lithium sulfur dioxide cells wired in series.
- 3. Batteries three and four each have two L032S lithium sulfur dioxide cells wired in series.

All cells used in this test program were manufactured by Duracell International, Inc.

Batteries one and two each have a thermal fuse (80-90°C) and a four ampere fuse in the ground leg. Batteries three and four each have a three ampere fuse in the ground leg. This combination of fuses protects against short circuit and excessive discharge rates.

最近世界は記念れた。他は日本地ではただがなど、中国には

¹NAVSEAINST 9310.1, March 1979.

CHAPTER 2

EXPERIMENTAL

The experimental program was conducted as follows:

のことには、100mmのでは、100m

- The four latteries of the pack were simultaneously short-circuited inside the "PHOTO FINISH" housing with all fuses bypassed. Voltages, currents, temperatures, and pressures were monitored throughout the run. This test was repeated three times.
- 2. The four batteries of the pack were simultaneously discharged at the fuse values with an external D.C. constant current power supply. For example, batteries one and two were discharged at four amperes, and batteries three and four at three amperes. Three discharges were carried out at ambient temperatures (10-25°C) and one with the buoy preheated to 71°C. Voltages, temperatures, and pressures were monitored throughout the run.
- 3. The third set of tests conducted was external heating of the battery pack by wrapping heat tape around the "PHOTO FINISH" unit in the vicinity of the battery pack.

Pressures were measured using a Standard Controls Model Number 1200-41-1 pressure transducer. Type K thermocouples were used to measure the temperatures at several points on the package containing the four batteries. Thermocouple location on the complete battery package and "PHOTO FINISH" housing is indicated in Figure 1. A photograph of the battery package is shown in Figure 2.

Video tapes and high speed movies were made on all tests and are on file at the Naval Surface Weapons Center, White Oak.




FIGURE 1 SCHEMATIC OF "PHOTO FINISH" SHOWING LOCATION OF THERMOCOUPLES AND PRESSURE TRANSDUCER AS POSITIONED FOR TEST.



FIGURE 2 PHOTOGRAPH OF BATTERY PACKAGE. THE POWER SUPPLIES USED TO POWER "PHOTO FINISH" ARE CONTAINED INSIDE THIS PACKAGE.

CHAPTER 3

RESULTS AND DISCUSSION

The first series of tests was simultaneous short-circuiting of all four batteries within the pack (all fuses bypassed) through 0.4 ohm loads. The above test was repeated three times. All three tests resulted in venting of the batteries. However, the first two tests resulted in low housing pressure upon venting. A post mortem of these units indicated that the housing leaked where the thermocouples and voltage leads exited the unit. The problem was corrected and a third short circuit test was run. The results of the third run are presented in Figure 3. Maximum pressure observed is 11 psig. The ventings caused the nose cap to be ejected at approximately 10 ft/sec. This velocity was measured using high speed photography and video techniques. After nose cap ejection the float bag inflated and subsequently bursted. A summary of the short circuit data is presented in Table 1.

The second series of tests was simultaneous discharge of the four batteries at the fuse value using four D.C. power supplies. As in short circuit, all fuses were bypassed. Batteries one and two had thirteen and four LO26SH cells in series respectively. Batteries three and four each had two LO32S cells in series. Batteries one and two were discharged at four amperes while three and four were discharged at three amperes. All discharges took place at room temperature except for discharge 033001 where the buoy was preconditioned at 71°C. The results are presented in Figures 4-7. A summary of the capacities observed along with the maximum temperature observed are presented in Table 2. All four tests resulted in nose cap ejection and float bag rupture. Batteries three and four were the first to vent. In all cases the venting of batteries three and four caused the housing pressure to increase to five psig. Nose cap ejection only occurred when batteries one and two vented. A summary of the pressure and nose cap ejection velocities is presented in Table 3.

The last series of tests conducted was external heating of the battery pack by wrapping heat tape around the "PHOTO FINISH" unit in the vicinity of the battery pack. A photograph of "PHOTO FINISH" with the heat tape in place is shown in Figure 8. As in the previous tests, all fuses were bypassed. This test was repeated. The results of the heating test are presented in Figures.9 and 10. External heating forced the batteries to vent and caused a nose cap ejection similar to short circuit and constant current discharge.






TABLE 1 SUMMARY OF SHORT CIRCUIT DATA ON "PHOTO FINISH" THROUGH 0.4 OHM LOAD

TEST NUMBER	BATTERY 1	NUMBER AND	MAXIMUM 3	CURRENT 4	BATTERY PACK TEMPERATURE (°C)
224001	53.4	12.2	9.0	6.2	
224002	54.0	14.0	6.0	6.0	110
032001	40.5	17.5	7.5	7.0	267




3-4



TEMPERATURE (°C)


3-5



THE PARTIES OF THE PROPERTY OF THE PROPERTY OF THE PARTIES OF THE

FIGURE 6 SIMULTANECUS CONSTANT CURREST DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERIS WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOSIN

THE POST OF THE POST OF THE PAST OF THE PA



ではない。

開発的の対応対応機能はないないない。 単語ななならなる 自身が アンプラン ちょうこうてき できる

SIMULTANEUUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TYO WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN. THE ENTIRE "PHOTO FINISH" UNIT WAS PRECONDITIONED AT 71°C PRIOR TO DISCHARGE. FIGURE 7

TABLE 2 CAPACITY IN AMPERE HOURS OF "PHOTO FINISH" BATTERIES TO A 2 VOLT/CELL CUTOFF

TEST NUMBER	BATT 1	ERY NUMBER 2	AND CAPAG	CITY 4	MAXIMUM BATTERY PACK TEMPERATURE (°C)
226001	3.05	3.30	0	0	291
227001	5.60	5.67	0.3	0.3	152
227002	5.03	5.03	0.12	0.12	. 605
033001	4.27	4.53	0.13	0.13	814

CONTROL CONTRO

TABLE 3 MEASURED VELOCITY AT WHICH NOSE CAP WAS EJECTED.
MAXIMUM PRESSURSS ARE ALSO SUMMARIZED

TEST NUMBER	MEASURED VELOCITY	(IN FT/SEC) AT 1' ANI and 8'	MAXIMUM PRESSURE (psig)
			. 0
225001			23.0
226001		***	11.0
	•		
227001	24	20	23.0
227002	16	12	14.9
022001	10		11.0
032001	10		11.0
032002	24	19	30.0
V72VV2	67	1,7	50.0
033001	4	,	12.0






FIGURE 8 PHOTOGRAPH OF "PHOTO FINISH" UNIT WITH HEAT TAPE *N VICINITY OF BATTERY PACK



10°C/MINUTE. BATTERY TEMPERATURE, VOLTAGES OF EACH BATTERY AND HOUSING PRESSURE ARE PLOTTED THE BATTERY WAS HEATED AT APPROXIMATELY RESULTS OF EXTERNAL HEATING OF "PHOTO FUNISH". FIGURE 9



3-12

Park to the transfer of the same and the same

CHAPTER 4

CONCLUSIONS

The tests results presented in this report indicate that nose cap ejection will take place under "worst case" conditions. However, no fires were observed under any of the tests conducted.

Based upon the tests results and the scenario of use, the following recommendations should enhance the safety of "PHOTO FINISH" units:

1. Label the batteries in accordance with reference 1.

THE POLICY COMPANY WASHINGTON TO STATE OF THE POLICY OF TH

- 2. Reduce the three ampere fuse in batteries three and four to approximately one ampere.
- 3. Store batteries separately from the "PHOTO FINISH" units until minety days prior to deployment.
- 4. After the batteries are loaded into the units, a CAUTION label in accordance with Figure 1 of reference (1) should be placed on both the unit and the grey overpack.
- 5. Do not remove units from grey overpack greater than fifteen days prior to deployment.
- 6. A warning notice to handling personnel should be placed on the units that after the batteries are loaded, a possibility exists for nose cap ejection.
- 7. The "PHOTO FINISH" units are to be loaded into the launch tubes only, and not stored inside the aircraft.

DISTRIBUTION

	Copies	<u>(</u>	Copies
Defense Technical Information Center		Commander Naval Weapons Center	
Cameron Station		Attn: Code 38 (E. Royce)	1
Alexandria, VA 22314	12	Code 3352 (A. Fletcher)	1
, , , , , , , , , , , , , , , , , , ,		Mr. L. Pracchia	ì
Commander		China Lake, CA 93555	_
Naval Sea Systems Command		diana caro, on 55555	
Attn: SEA OGR (D. J. Pastine	1	Office of Naval Research	
SEA 63R3 (F. Romano)	ī	Attn: ONR 472 (G. Neece)	1
SEA 9823	ī	ONR 472 (J. Smith)	1
SEA 06H (E. Daugherty)	2	800 N. Quincy Street	.
SEA 09G32	2	Arlington, VA 22217	
SEA 921AN	_	The same of the sa	
(LCDR K. A. Tobin)	1	Commander	
NAVSEA 543	1	Naval Weapons Support Center	
Washington, DC 20362	-	Electrochemical Power Sources Division	
Commander		Attn: Code 305 (M. Robertson)	1
Naval Ocean Systems Center		Code 3061 (S. Shuler)	1
Attn: Code 922	1	Crane, IN 47522	*
Code 712 (J. McCartney)	ī		
Code 6343 (S. Spazk)	ī	Commander	
San Diego, CA 92152	_	Naval Electronics Systems Command Attn: Code PME 124-31	i
Commander		(A. H. Sobel)	1
Naval Intelligence Support Center	r	NAVELEX O1K (A. Sliwa)	î
Attn: Code 362 (H. Ruskie)	1	40736 (W. J. Weingartner)	***
Washington, DC 20390	_	Washington, DC 20360	
Office of Navy Technology		Commander	
Associate Director		Naval Air Development Center	
Attn: Support Technology (072)	1	Attn: Library	1
800 N. Quincy Street Arlington, VA 22217	•	Warminster, PA 18974	
		Commander	
Chief of Naval Operations .		Naval Underwater Systems Center	
Operating Evaluation Group Washington, DC 20350	1	Attn: Code 3642 (R. Lazar) (J. Moden)	2
		Namont DI 02840	

DISTRIBUTION (Cont.)

9	Copies		Copies
David W. Taylor Naval Ship Research and Development Center Annapolis Laboratory	n	Honeywell Inc. Defense Systems Division Power Sources Center	
Attn: Code 2724 (H. R. Urbach) Annapolis, MD 21401	1	Attn: Library 104 Rock Road Horsham, PA 19044	. 1
U. S. Army HQDA-DAEN-ASR-SL	_		
Attn: Charles Scuilla Washington, DC 20314	1	Yardney Electric Corporation Attn: Library 82 Mechanic Street	1
U. S. Army Electronics Command	1	Pawcatuck, CT 02891	
Attn: Code DELET P (T. Reiss) Code DRSEL-TR-PR	.	Duracell International	
(Dr. S. Gilman)	1	Attn: B. McDonald	1
Fort Monmouth, NJ 07703		South Broadway Tacrytown, NY 10591	
Air Force Aero Propulsion Lab	•	n 11 Turanatana1	
Attn: AFAPL/OPE-1 (W : Bishop) (b. Marsh)	1	Duracell International Laboratory for Physical Science	
Wright-Patterson AFB, OH 45433	1	Attn: Library	1
		Burlington, MA 01803	
Headquarters			
Department of Transportation		Power Conversion Inc.	
U. S. Coast Guard		70 MacQuesten Parkway South	1
Ocean Engineering Division Attn: GEOE-3/61 (R. Potter)	1	Mount Vernon, NY 10550	•
Washington, DC 20590	*	Eagle-Picher Industries	
		Couples Department	
NASA Goddard Space Flight Center		Attn: Library	1
Attn: Code 711 (G. Halpert) Hampton, VA 23665	1	Joplin, MO 64801	
		Sparton Electronics	•
NASA Johnson Space Center		Attn: Carroll H. Bush	1
NASA Rd 1	7	2400 East Ganson Street Jackson, MI 49202	
Attn: Code EPS (B, J, Bragg) Houston, TX 77058	1		
Lockheed Palo Alto Research		Sonatech Inc. Attn: Reggie Sear	1
Laboratory		700 Francis Botello Road	
Lockheed Missile & Space Co., Inc.		Goleta, CA 93017	
Attn: Library	1	·	
3251 Hanover Strewt		Sanders Associates, Inc.	
Palo Alto, CA 94304		Attn: George Disco	1
Altus Comonacion		95 Canal Street Nashua, NH 03061	
Altus Corporation 1610 Crane Court		nedings un Adant	
San Jose, CA 95112	1		
•			

DISTRIBUTION (Cont.)

	Copies	•	Copies
Electrochem Industries, Inc. Attn: Dr. Robert Murphy	1	McDonnell Douglas Corporation 1150 17th Street, N.W.,	
9990 Wehrle Drive Clarence, NY 14031		Suite 500 Washington, DC 20036	1
Magnavox Company Department 529		EIC Corporation	•
Attn: Carl Keuneke	1	Attn: Dr. K. M. Abraham 55 Chapel Street	1
1313 Production Road	•	Newton, MA 02158	
Fort Wayne, IN 46808			
• •		General Electric Co.	
Ray-0-Vac		Attn: Dr. R. W. Race, Manager	
Attn: R. F. Udell	1	Advance Programs Marketing	š
B. C. Bergum	1	Room 2544A - OP#2	1
101 East Washington Avenue		100 Plastics Avenue	
Madison, WI 53703		Pittsfield, MA 01201	
Gould, Inc.		Norton Air Force Base	
Gould Laboratories		Attn: Code BMO/ENBE	
40 Gould Center		(Capt. A. S. Alanis)	7
Rolling Meadows, IL 60000	1	Code AFISC/SES	1
	_	Norton AFB, CA 92409	•
The Boeing Company		·	
Attn: Dr. A. C. Johnson	1	Honeywell Power Sources Center	
P. O. Box 3707	,	Attn: Dr. David L. Chua	
Seattle, WN 98124		104 Rock Road	
CTF 1 shometoniae I		Horsham, PA 19044	
GTE Laboratories, Inc. Attn: Library	•	Bathama Barina '	
40 Sylvan Road	1	Battery Engineering Attn: Dr. N. Marincic	•
Waltham, MA 02154		80 Oak Street	1
version and versio		Newton, MA 02164	
Martin Marietta Aerospace		, ,	
Attn: John W. Wear	1	NOAA Data Buoy Center	
P.O. Box 179		Attn: Mr. D. Scully	1
Denver, CO 80201		NSTL STATION, MS 39529	
GTE Sylvania		Mala Janes Miller	
Attn: Dr. Robert McDonald	1	Teledyne Electronics Attn: Mr. G. Lamb	,
189 B Street	•	649 Lawrence Drive	1
Needham Heights, MA 02194		Newbury Park, CA 91320	
Navy Environmental Health Center		Mare Island Naval Ship Yard	
Attn: J. R. Crawl, Head	,	Attn: Code 280.08	1
Hazardous Mat. Eval Br. Naval Station	1	Stop 060 (R. Houlder)	1
Norfolk, VA 23511		Vallejo, CA 94592	
ivervan, in acces			

DISTRIBUTION (Cont.)

	Copies	·	Copies
The Aerospace Corporation Attn: Mr. Albert Heller 2350 East El Segundo Blvd. P. O. Box 92957 Los Angeles, CA 90009	1	Acoustic Systems, Inc. Attn: Dr. James Fish 600 Norman Firestone Rd. Goleta, CA 93117	1
Internal Distribution:			
R30 R33 R33 (Bis) E35 E431 E432	1 70 1 9 3		